





Selection Chart



Three Phase






Three Phase



50CSH6.4 (1/2HP)
Synchronous Speed: 3600 RPM
2 inch Discharge

50CSH6.75 (1HP)
Synchronous Speed: 3600 RPM
2 inch Discharge


50CSH61.5 (2HP)
Synchronous Speed: 3600 RPM
2 inch Discharge

50CS62.2 50CSH62.2 (3HP) Synchronous Speed: 3600 RPM
2 inch Discharge


50CS63.7 50CSH63.7 (5HP) Synchronous Speed: 3600 RPM
2 inch Discharge

80CS62.2 80CSH62.2 (3HP) Synchronous Speed: 3600 RPM
3 inch Discharge


80CS63.7 80CSH63.7 (5 HP) Synchronous Speed: 3600 RPM
3 inch Discharge

100CS65.5 (7½ HP)
Synchronous Speed: 3600 RPM
4 inch Discharge
